## SELITUDE

## Service History Report

August 9, 2019 50097

## Southern Hills CID

Date Range: 07/01/19..07/31/19

Toll Free: (888) 480-523 Fax: (888) 358-003 www.solitudelakemanag	88					
Service Date				S0385		
No. PI-A00282		PI-A00282955				
Order No. SMOR-25		SMOR-253613				
Contract No.	S	SVR11453				
Technician Name and Sta						
	Jordan Hathaway					
Service Item #	Description	Lake No.	Lake Name			
S0385-LAKE-001	Southern Hills CID Lake		Lake 1			
Technician's Comments:	Treated for heavy algae. Will be back next week to hit again. Got really goodcoverage should should see results in five days					
General Comments:	Inspected Lake					
Inspected for Aquatic Weeds			OK			
Inspected for algae			Treated			
Inspected for Undesirable S	Shoreline Vegetation		Treated			
Service Item #	Description	Lake No.	Lake Name			
S0385-LAKE-002	Southern Hills CID Lake 2	<b>2</b> 2	Lake 2			
Technician's Comments:	Treated for some light alga	e around the shoreline. Will co	ntinue to monitor andtreat as needed.			
General Comments:	Inspected Lake					
Inspected for Aquatic Weeds			ОК			
Inspected for Undesirable S	Shoreline Vegetation		ОК			
Inspected for algae			Treated			
======================================				 S0385		
No.		PI-A00284171		00000		
Order No.		SMOR-262550				
Contract No.		SVR11453				
Technician Name and Sta	te License #s					
	Jordan Hathaway Daniel Williams					
Service Item #	Description	Lake No.	Lake Name			
S0385-LAKE-001	Southern Hills CID Lake	<b>1</b> 1	Lake 1			
Technician's Comments:	Lake was looking much better. Treated again for algae on surface, and also didan injection into the water to try and kill faster at the root. Will continue tomonitor and treat as needed.					
General Comments:	Inspected Lake					
Inspected for Aquatic Weeds			ОК			
Inspected for algae			Treated			
Inspected for Undesirable Shoreline Vegetation			Treated			

	Description	Lake No.	Lake Name		
S0385-LAKE-002	Southern Hills CID Lake 2	2	Lake 2		
General Comments:	Inspected Lake				
Inspected for Aquatic Weed	ls		ОК	ОК	
Inspected for Undesirable S	Shoreline Vegetation		ОК		
Inspected for algae			ОК		
Service Date	7/*	18/2019		S0385	
No.	PI-A00284110				
		/OR-262549			
Contract No.		/R11453			
Technician Name and Sta					
Convice Item #	Jordan Hathaway		Laka Nama		
Service Item # S0385-LAKE-001	Description Southern Hills CID Lake 1	Lake No. 1	Lake Name Lake 1		
Technician's Comments:			s for the comingmonths. I treated for heavy algae	and primrose around the	
	lake. I will be backnext week		e let the comingmontals. I treated for heavy digde		
General Comments:	Inspected Lake				
Inspected for Aquatic Weed	ls		ОК		
Inspected for algae			Treated		
Inspected for Undesirable S	Shoreline Vegetation		Treated		
Service Item #	Description	Lake No.	Lake Name		
S0385-LAKE-002	Southern Hills CID Lake 2	2	Lake 2		
Technician's Comments:	lake was looking good. Treat	ed for some algae around	the shoreline of the lake.		
General Comments:	Inspected Lake				
Inspected for Aquatic Weed	ls		ОК		
Inspected for Undesirable S			ОК	OK	
Inspected for algae	0		Treated		
	\=================================				
Service Date		31/2019		S0385	
	7/3	<b>31/2019</b> A00289213		S0385	
Service Date	<b>7/</b> 3 Pl·			S0385	
Service Date No.	7/3 Pi SM	A00289213		S0385	
Service Date No. Order No.	7/3 Pi- SN SV te License #s	A00289213 IOR-263206		S0385	
Service Date No. Order No. Contract No. Technician Name and Sta	7/3 Pi- SM SV <b>te License #s</b> Jordan Hathaway	A00289213 /IOR-263206 /R11453		S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item #	7/3 Pi- SM SV te License #s Jordan Hathaway Description	A00289213 MOR-263206 /R11453 Lake No.	Lake Name	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001	7/3 Pi- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1	A00289213 MOR-263206 /R11453 Lake No. 1	Lake Name Lake 1	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments:	7/3 PI- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p	A00289213 MOR-263206 /R11453 Lake No. 1	Lake Name	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments: General Comments:	7/3 Pi- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake	A00289213 MOR-263206 /R11453 Lake No. 1	Lake Name Lake 1 up and dying. I willcontinue to treat as needed.	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments:	7/3 Pi- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake	A00289213 MOR-263206 /R11453 Lake No. 1	Lake Name Lake 1	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments: General Comments:	7/3 Pi- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake	A00289213 MOR-263206 /R11453 Lake No. 1	Lake Name Lake 1 up and dying. I willcontinue to treat as needed.	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments: General Comments: Inspected for Aquatic Weed	7/3 Pi- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake	A00289213 MOR-263206 /R11453 Lake No. 1	Lake Name Lake 1 up and dying. I willcontinue to treat as needed. OK	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments: General Comments: Inspected for Aquatic Weed Inspected for Algae	7/3 Pi- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake	A00289213 MOR-263206 /R11453 Lake No. 1	Lake Name Lake 1 up and dying. I willcontinue to treat as needed. OK Treated	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments: General Comments: Inspected for Aquatic Weed Inspected for algae Inspected for undesirable S Service Item #	7/3 Pi- SM SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake ds Shoreline Vegetation Description	A00289213 MOR-263206 /R11453 Lake No. 1 rimrose. Algae is breaking Lake No.	Lake Name Lake 1 up and dying. I willcontinue to treat as needed. OK Treated Treated Lake Name	S0385	
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments: General Comments: Inspected for Aquatic Weed Inspected for Aquatic Weed Inspected for Undesirable S Service Item # S0385-LAKE-002	7/3 Pi- SN SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake ds Shoreline Vegetation Description Description Southern Hills CID Lake 2	A00289213 MOR-263206 /R11453 Lake No. 1 rimrose. Algae is breaking Lake No. 2	Lake Name Lake 1 up and dying. I willcontinue to treat as needed. OK Treated Treated Lake Name Lake 2		
Service Date No. Order No. Contract No. Technician Name and Sta Service Item # S0385-LAKE-001 Technician's Comments: General Comments: Inspected for Aquatic Weed Inspected for algae Inspected for undesirable S Service Item #	7/3 Pi- SN SV te License #s Jordan Hathaway Description Southern Hills CID Lake 1 Treated for algae and light p Inspected Lake ds Shoreline Vegetation Description Description Southern Hills CID Lake 2	A00289213 MOR-263206 /R11453 Lake No. 1 rimrose. Algae is breaking Lake No. 2	Lake Name Lake 1 up and dying. I willcontinue to treat as needed. OK Treated Treated Lake Name		

Inspected for Aquatic Weeds	OK
Inspected for Undesirable Shoreline Vegetation	ОК
Inspected for algae	Treated