SELITUDE

Toll Free: (888) 480-5253

Service History Report

May 8, 2020 50097

Southern Hills CID

Date Range: 04/01/20..04/30/20

Service Date	4/15/20	020	S038		
No.	PI-A00	393402			
Order No.	SMOR	-327540			
Contract No.	SVR47	/097			
Technician Name and Sta	te License #s				
	Jordan Hathaway				
Service Item #	Description	Lake No.	Lake Name		
S0385-LAKE-001	Southern Hills CID Lake 1	1	Lake 1		
Technician's Comments:	Treated for algae above and growth beneath the surface. I grabbed a sample ofwhat is growing beneath the surface, since my treatments have not been doingmuch it. I will have a better treatment regime next visit.				
General Comments:	Inspected Lake				
Inspected for Aquatic Weed	ds		ОК		
Inspected for algae			Treated		
Inspected for Undesirable Shoreline Vegetation			ОК		
Biological / Microbial Applic	cation		Added		
Preventative Aquatic Weed	Control Treatment		added the last two visits		
Service Item #	Description	Lake No.	Lake Name		
S0385-LAKE-002	Southern Hills CID Lake 2	2	Lake 2		
Technician's Comments:	Everything was looking pretty go to monitor and treat asneeded.	od. I treated for some lig	ht algae and addedsome bio to help break down some muck. I will continu		
General Comments:	Inspected Lake				
Inspected for Aquatic Weeds			ОК		
Inspected for Undesirable Shoreline Vegetation			ОК		
Inspected for algae			Treated		
Biological / Microbial Applic	cation		Added		
Preventative Aquatic Weed	Control Treatment		apply next visit		
Service Item #	Description	Lake No.	Lake Name		
S0385-NANO-001	SLM Owned Nanobubble Clear	1 50 1	Lake 1		
Technician's Comments:	Nano bubble was clogged up in the basket inside the pump. I cleared it out andthe basket in the water and everything is running great. If a resident ever seesthe outflow line floating at the surface, it means the system is not running atfull capacity.				
General Comments:	Serviced Aeration System				

 Service Date
 4/30/2020

 No.
 PI-A00399371

 Order No.
 SMOR-334129

 Contract No.
 SVR47097

 Technician Name and State License #s
 SVR47097

S0385

Service Item #	Description	Lake No.	Lake Name		
S0385-LAKE-001	Southern Hills CID Lake 1	1	Lake 1		
Technician's Comments:	Treated for algae and southern niad. The sonar should start to take effect soonand start really killing it off. I will continue to monitor and treat as needed.				
General Comments:	Inspected Lake				
Inspected for Aquatic Weeds		Treated			
Inspected for algae		Treated			
Inspected for Undesirable Shoreline Vegetation			ОК		

Service Item #	Description	Lake No.	Lake Name	
S0385-LAKE-002	Southern Hills CID Lake 2	2	Lake 2	
Technician's Comments:	Everything was looking pretty good. I treated for light algae around the pond. Iwill continue to monitor and treat as needed.			
General Comments:	Inspected Lake			
Inspected for Aquatic Weeds			ОК	
Inspected for Undesirable Shoreline Vegetation			OK	
Inspected for algae			Treated	